FZ	Fusion Zone
GCZ	Grain Coarsening Zone
GRZ	Grain Refinement Zone

Greek symbols

α	α-ferrite grains
P	brownish pearlite